

Batches of raw material	Operators				
	1	2	3	4	5
1	A=24	B=20	C=19	D=24	E=24
2	B=17	C=24	D=30	E=27	A=36
3	C=18	D=38	E=26	A=27	B=21
4	D=26	E=31	A=26	B=23	C=22
5	E=22	A=30	B=20	C=29	D=31